

Februar 1973		Umrechnungstabelle für Brüche von 1" englisch				03.00.05	
Bruch		Dezimal	mm	Bruch		Dezimal	mm
1/128		.00781	0.1984	33/64		.515625	13.0969
1/64		.015625	0.3969	34/64	17/32	.53125	13.4938
2/64	1/32	.03125	0.7938	35/64		.546875	13.8906
3/64		.046875	1.1906	36/64	9/16	.5625	14.2875
4/64	1/16	.0625	1.5875	37/64		.578125	14.6844
5/64		.078125	1.9844	38/64	19/32	.59375	15.0812
6/64	3/32	.09375	2.3812	39/64		.609375	15.4781
7/64		.109375	2.7781	40/64	5/8	.625	15.8750
8/64	1/8	.125	3.1750	41/64		.640625	16.2719
9/64		.140625	3.5719	42/64	21/32	.65625	16.6688
10/64	5/32	.15625	3.9688	43/64		.671875	17.0656
11/64		.171875	4.3656	44/64	11/16	.6875	17.4625
12/64	3/16	.1875	4.7625	45/64		.703125	17.8594
13/64		.203125	5.1594	46/64	23/32	.71875	18.2562
14/64	7/32	.21875	5.5562	47/64		.734375	18.6531
15/64		.234375	5.9531	48/64	3/4	.75	19.0500
16/64	1/4	.25	6.3500	49/64		.765625	19.4469
17/64		.265625	6.7469	50/64	25/32	.78125	19.8438
18/64	9/32	.28125	7.1438	51/64		.796875	20.2406
19/64		.296875	7.5406	52/64	13/16	.8125	20.6375
20/64	5/16	.3125	7.9375	53/64		.828125	21.0344
21/64		.328125	8.3344	54/64	27/32	.84375	21.4312
22/64	11/32	.34375	8.7312	55/64		.859375	21.8281
23/64		.359375	9.1281	56/64	7/8	.875	22.2250
24/64	3/8	.375	9.5250	57/64		.890625	22.6219
25/64		.390625	9.9219	58/64	29/32	.90625	23.0188
26/64	13/32	.40625	10.3188	59/64		.921875	23.4156
27/64		.421875	10.7156	60/64	15/16	.9375	23.8125
28/64	7/16	.4375	11.1125	61/64		.953125	24.2094
29/64		.453125	11.5094	62/64	31/32	.96875	24.6062
30/64	15/32	.46875	11.9062	63/64		.984375	25.0031
31/64		.484375	12.3031	64/64	1	1.-	25.4000
32/64	1/2	.5	12.7000				

Tabellen Wärmetechnik